

# RM5

# Ferrite core

Series/Type: B65805 Ordering code: B65805J0160A087

1

Date: Version: 2015-08-04

© EPCOS AG 2015. Reproduction, publication and dissemination of this publication, enclosures hereto and the information contained therein without EPCOS' prior express consent is prohibited.

EPCOS AG is a TDK Group Company.

# **②TDK**

# B65805J0160A087

### B65805

# Magnetic characteristics (per set)

ΣI/A	=	0.93 mm <sup>-1</sup>	
l <sub>e</sub>	=	22.1 mm	
A <sub>e</sub>	=	23.8 mm <sup>2</sup>	
$A_{min}$	=	18 mm <sup>2</sup>	
Ve	=	526 mm <sup>3</sup>	

## Approx. weight


3.0 g/set

RM5

**Ferrite core** 

### **Delivery mode**

In sets



# Packing

Blister

Material	A <sub>L</sub> value <sup>1)</sup>	μ <sub>e</sub>	Air gap	Ordering code
	nH		mm	-J without center hole
N87	160 ±3 %	118	0.18	B65805J0160A087

1) Measurement parameter: 10 kHz, 0.25 mT, 100 turns, test force 20N, room temperature.

 $A_{L}$  value is measured acc. to IEC62044-2. An appropriate wringing of cores with polished surface is used to improve reproducibility of the measurement. (It is recommended to rub the mating surfaces themselves six times in a circular or elliptic arc that matches the core profile before measuring  $A_{L}$  value).



# RM5

### **Ferrite core**

### **Cautions and warnings**

#### Mechanical stress and mounting

Ferrite cores have to meet mechanical requirements during assembling and for a growing number of applications. Since ferrites are ceramic materials one has to be aware of the special behavior under mechanical load.

As valid for any ceramic material, ferrite cores are brittle and sensitive to any shock, fast changing or tensile load. Especially high cooling rates under ultrasonic cleaning and high static or cyclic loads can cause cracks or failure of the ferrite cores.

For detailed information see Data Book 2007, chapter "General – Definitions, 8.1".

#### Effects of core combination on AL value

Stresses in the core affect not only the mechanical but also the magnetic properties. It is apparent that the initial permeability is dependent on the stress state of the core. The higher the stresses are in the core, the lower is the value for the initial permeability. Thus the embedding medium should have the greatest possible elasticity. For detailed information see Data Book 2007, chapter "General – Definitions, 8.2".

#### Heating up

Ferrites can run hot during operation at higher flux densities and higher frequencies.

#### **NiZn-materials**

The magnetic properties of NiZn-materials can change irreversible in high magnetic fields.

#### Processing notes

The start of the winding process should be soft. Else the flanges may be destroyed.

To strong winding forces may blast the flanges or squeeze the tube that the cores can no more be mount.

To long soldering time at high temperature (>300 °C) may effect coplanarity or pin arrangement.

Not following the processing notes for soldering of the J-leg terminals may cause solderability problems at the transformer because of pollution with Sn oxide of the tin bath or burned insulation of the wire. For detailed information see Data Book 2007, chapter "Processing notes, 2.2".

The dimensions of the hole arrangement have fixed values and should be understood as a recommendation for drilling the printed circuit board. For dimensioning the pins, the group of holes can only be seen under certain conditions, as they fit into the given hole arrangement. To avoid problems when mounting the transformer, the manufacturing tolerances for positioning the customers' drilling process must be considered by increasing the hole diameter.