


# Accessories

## Auxiliary contact


### Front mount blocks

### Side mount blocks


#### Screw clamp connection




#### Fast-on connection



#### Cage clamp connection



#### Solder pin connection



## Catalog No.

| Connection type    | Applying contactors   | Mounting type | Composition | Catalog no. |
|--------------------|---|---------------|-------------|-------------|
| <b>Screw clamp</b> | CGMS-, CGMSS-, CGMUS-<br>6A(D)<br>9A(D)<br>12A(D)<br>16A(D) | Front mount   | 2NO         | AX-2MS20    |
|                    |   |               | 2NC         | AX-2MS02    |
|                    |   |               | 1NO+1NC     | AX-2MS11    |
|                    |   |               | 4NO         | AX-4MS40    |
|                    |   |               | 3NO+1NC     | AX-4MS31    |
|                    |   |               | 2NO+2NC     | AX-4MS22    |
|                    |   |               | 1NO+3NC     | AX-4MS13    |
|                    |   |               | 4NC         | AX-4MS04    |
|                    |   |               | Side mount  | 1NO         |
|                    |   | 1NC           | AX-1MS01    |             |
| <b>Fast-on</b>     | CGMF-, CGMSF-, CGMUF-<br>6A(D)<br>9A(D)<br>12A(D)<br>16A(D) | Front mount   | 2NO         | AX-2MF20    |
|                    |   |               | 2NC         | AX-2MF02    |
|                    |   |               | 1NO+1NC     | AX-2MF11    |
|                    |   |               | 4NO         | AX-4MF40    |
|                    |   |               | 3NO+1NC     | AX-4MF31    |
|                    |   |               | 2NO+2NC     | AX-4MF22    |
|                    |   |               | 1NO+3NC     | AX-4MF13    |
|                    |   |               | 4NC         | AX-4MF04    |
|                    |   |               | Side mount  | 1NO         |
|                    |   | 1NC           | AX-1MF01    |             |
| <b>Cage clamp</b>  | CGMC-, CGMSC-, CGMUC-<br>6A(D)<br>9A(D)<br>12A(D)<br>16A(D) | Front mount   | 2NO         | AX-2MC20    |
|                    |   |               | 2NC         | AX-2MC02    |
|                    |   |               | 1NO+1NC     | AX-2MC11    |
|                    |   |               | 4NO         | AX-4MC40    |
|                    |   |               | 3NO+1NC     | AX-4MC31    |
|                    |   |               | 2NO+2NC     | AX-4MC22    |
|                    |   |               | 1NO+3NC     | AX-4MC13    |
|                    |   |               | 4NC         | AX-4MC04    |
|                    |   |               | Side mount  | 1NO         |
|                    |   | 1NC           | AX-1MC01    |             |
| <b>Solder pin</b>  | CGMP-, CGMSP-, CGMUP-<br>6A(D)<br>9A(D)<br>12A(D)<br>16A(D) | Side mount    | 1NO         | AX-1MP10    |
|                    |   |               | 1NC         | AX-1MP01    |
|                    |   |               |             |             |
|                    |   |               |             |             |
|                    |   |               |             |             |