

# Accessories

## Auxiliary contact

### Front mount blocks

### Side mount blocks


#### Screw clamp connection



AX-4MS, 4pole



AX-2MS, 2pole



AX-1MS, 1pole


#### Fast-on connection



AX-4MF, 4pole




AX-2MF, 2pole



AX-1MF, 1pole


#### Cage clamp connection



AX-4MC, 4pole




AX-2MC, 2pole



AX-1MC, 1pole

#### Solder pin connection



AX-1MS, 1pole

## Catalog No.

Connection type	Applying contactors	Mounting type	Composition	Catalog no.
<b>Screw clamp</b>	CGMS-, CGMSS-, CGMUS- 6A(D) 9A(D) 12A(D) 16A(D)	Front mount	2NO	AX-2MS20
			2NC	AX-2MS02
			1NO+1NC	AX-2MS11
			4NO	AX-4MS40
			3NO+1NC	AX-4MS31
			2NO+2NC	AX-4MS22
			1NO+3NC	AX-4MS13
			4NC	AX-4MS04
			Side mount	1NO
		1NC	AX-1MS01	
<b>Fast-on</b>	CGMF-, CGMSF-, CGMUF- 6A(D) 9A(D) 12A(D) 16A(D)	Front mount	2NO	AX-2MF20
			2NC	AX-2MF02
			1NO+1NC	AX-2MF11
			4NO	AX-4MF40
			3NO+1NC	AX-4MF31
			2NO+2NC	AX-4MF22
			1NO+3NC	AX-4MF13
			4NC	AX-4MF04
			Side mount	1NO
		1NC	AX-1MF01	
<b>Cage clamp</b>	CGMC-, CGMSC-, CGMUC- 6A(D) 9A(D) 12A(D) 16A(D)	Front mount	2NO	AX-2MC20
			2NC	AX-2MC02
			1NO+1NC	AX-2MC11
			4NO	AX-4MC40
			3NO+1NC	AX-4MC31
			2NO+2NC	AX-4MC22
			1NO+3NC	AX-4MC13
			4NC	AX-4MC04
			Side mount	1NO
		1NC	AX-1MC01	
<b>Solder pin</b>	CGMP-, CGMSP-, CGMUP- 6A(D) 9A(D) 12A(D) 16A(D)	Side mount	1NO	AX-1MP10
			1NC	AX-1MP01